

Walled Garden From the Park/Proposed Band Stand



Existing 'new wall' replaced with railings to improve visual connection with the gardens & orangry

Access through to St. Marks Gate cleared & improved.


All existing vegetation inside & outside the walls cleared

Walled Garden From the Conservatory

View showing garden restored to circa. 1880's but with the addition of railings to replace the 'new' wall....
Seat detail relocated from the front of the orangery back to as close as possible to it's original position.
New seats fitted at front approach to orangery as per the original design,
Surrounding grass banks re-formed.
Additional benches as per original design.
Exsiting disabled access ramp removed and incorporated into north corner of the garden (see visual elsewhere).



Re-furbished Fountain



Full dismantle and re-build of fountain,
concrete base and surrounding parapet wall.
Paint to be removed.
Missing detailing re-made.
Fibreglass in fills removed and re made in
original material.
Supply re-connected.

Steps

Full dismantle and re-build
Paint to be removed.
Missing finials replaced.

Seat relocated to as close to original 1880's
position as possible, repaired, paint
removed.

Historic detail of grass bank to garden edge
re-formed
Additional benches as per original layout

nps group

NPS Group (Kendal)
Aynam Mills, Little Aynam
Kendal, Cumbria
LA9 7AH

New Disabled Ramp Access to Walled Garden

Disabled access removed from it's existing position to allow the garden to re-gain it's original layout and symetry. New ramp to be dug in & hidden behind the re-formed grass bank. Access provided from the lawn level via a re-formed path which was part of the original layout, approach to the ramp to replicate the existing steps detail. Ramp to follow the edge of the Orangerey to form one protected flank while the inside flank will be protected by guard rails to emmulate the style of the new conservatory, the same guard rail will also serve to enclose a protected 'outside space' for use by Age Concern. .



Re-furbished Porch to Walled Garden



Repairs to porch, gates & adjacent wall


Access through to St. Marks Gate cleared & improved.

Historic surfacing exposed and refurbished

nps group

NPS Group (Kendal)
Aynam Mills, Little Aynam
Kendal, Cumbria
LA9 7AH

Re-furbished Pond



Selective tree thinning to re-establish visual and physical link with Mansion House and the Bistro

Folly consolidated and interpretation provided re: it's original form and context

Selective tree thinning to re-establish visual and physical link with the walled garden, rose garden & bandstand area

Surrounding vegetation/trees to be thinned out to reduce shade and improve the visual aspect & the ecological value of the site.

New planting around pond edge to concentrate on marginal & semi-aquatic species to improve ecological value & water quality

Pond to be drained, cleared of silt/debris and concrete banks removed and re-built in sloping rough dress stone as per historic detail and to improve ecological value.

Surrounding railings re-paired/re-furbished and new seating provided as per original park layout.


All historic surfacing/edgings where evident to be exposed, and re-furbished.

nps/group

NPS Group (Kendal)
Aynam Mills, Little Aynam
Kendal, Cumbria
LA9 7AH

New Approach to Mansion House from City Road

Use of new surfacing/textures/patterns to strengthen the visual link to Mansion House and to enhance the line of the existing 'circuit path' around the edge of the park.



Re-formed City Road Entrance


Re-forming the former gates from City Road, removing the existing roadside pavement to promote footfall through the park and using the same surface treatment to enhance the visual/movement link with Mansion House



nps group

NPS Group (Kendal)
Aynam Mills, Little Aynam
Kendal, Cumbria
LA9 7AH

Re-furbished St Marks Entrance




Repair/refurbish existing railings and walls along Rutland Street & City Road

Repair/refurbish extg. pillars, reform gate and adjacent railings

Clear selected trees to enable a visual link with the roofline of Mansion House

Re-furbished Rose Garden



Removal of selected trees to open up views from & to the house

Clear extg vegetation and re-form as per 1880's with low shrubs/ground cover to open up views from & to the house

Re-form existing to rosesinken garden to it's original form



NPS Group (Kendal)
Aynam Mills, Little Aynam
Kendal, Cumbria
LA9 7AH


Re-furbished Windlehurst Gate



Selectiv thinning of adjacent vegetation to reduce enclosue and re-establish view onto the park

Repair/refurbish existing pillars & reform gate, some minor surface treatment to create focus up the drive into the park to enhance the route past the lodge building.

Re-furbished Balker Gate



Possible replacement of extg lights with traditional lanterns

Repair/consolidate existing wall, railings where exident to be repaired

Repair/refurbish existing pillars at Balker Gate

New Link between Bistro/Cafe & the Park

New outside seating area associated with the bistro and Mansion House with views over the folley & pond, A new path into the park will create the opportunity for increased physical & economic interaction between the building and the surrounding parkland.

